



RECESSED MOUNT



EVERY ATTEMPT HAS BEEN MADE TO ENSURE THE ACCURACY OF THIS DRAWING, HOWEVER VUTECH CANNOT BE HELD RESPONSIBLE FOR TYPOGRAPHICAL OR OTHER ERRORS.

RECESSED MOUNT ARTSCREEN PARTS LIST

| Item No. | Part No. | Description | Qty |
|-----------------|-----------------|---|------------|
| 1 | 190514 | Decorative Frame Assy, ArtScreen | 1 |
| 2 | 190502/507/509 | Roller Assy, ArtScreen 50"/42"/60" | 1 |
| 3 | 190511/512/513 | Welded Frame, Surface Mount 42"/50"/60" | 1 |
| 4 | 100401 | Motor, 404R2, LS40 120V ART SC | 1 |
| 5 | 100496 | Crown for Motor | 1 |
| 6 | 101158 | Mount Bracket, ArtScreen motor | 1 |
| 7 | 101157 | Bracket, Idler ArtScreen | 1 |
| 8 | 101010 | Standard Vibration Isolator, 70 Duro | 4 |
| | | Heavy Duty,Vibration Isolator | 4 |
| 9 | 100974 | Catch, Magnetic Surface Mount W/ Strike and Mount Screw | 1 |
| 10 | 600113 | Screw, Phil Pan, #10-32 X 1/2 | 4 |
| 11 | 600557 | Flat Washer, #10 | 12 |
| 12 | 100972 | Catch, Spring Loaded Grab | 1 |
| 13 | 100973 | Catch, Spring Loaded Grab w SPDT Switch | 1 |
| 14 | 600573 | Plain Flat Washer, #4 | 6 |
| 15 | 600570 | Lock Washer, #10 | 4 |
| 16 | 600116 | Screw, Phil Pan, #4-40 X 3/8 | 6 |
| 17 | 100636 | Tie Bar, for 37" Diagonal | 1 |
| | | Tie bar, for 42" & 43" Diagonal | 1 |
| | | Tie Bar for 50" Diagonal | 1 |
| | | Tie Bar for 55" Diagonal | 1 |
| | | Tie bar for 60" to 63" Diagonal | 1 |
| 18 | 190521 | Plasma Stand for 37" Diagonal | 2 |
| | | Plasma Stand for 42" & 43" Diagonal | 2 |
| | | Plasma Stand for 50" Diagonal | 2 |
| | | Plasma Stand for 55" Diagonal | 2 |
| | | Plasma Stand for 60" to 63" Diagonal | 2 |
| 19 | 600202 | Screw, Button HD, 1/4-20 X 3/4L | 4 |
| 20 | 600551 | Black Oxide Flat Washer 1/4-20 | 4 |
| 21 | 600530 | Hex Nut, #8-32 | 1 |
| 22 | 100984 | UHMW Flanged Bearing | 1 |
| 23 | 100497 | Idler for Motor MS4 | 1 |
| 24 | 100498 | Drive, MS4 Motor | 1 |
| 25 | 600111 | #8-32 x 3/8L Phil Pan Head Screw | 4 |
| 26A | 600564 | Fender Washer 1/4 I.D X 1 1/4 | 4 |
| 26B | 600563 | Fender Washer 3/16 I.D X 1 1/4 | 4 |
| 26C | 600565 | Fender Washer 5/16 I.D X 1 1/4 | 4 |
| 27A | 600207 | Screw, Button Hd, M4 X 12 | 4 |
| 27B | 600208 | Screw, Button Hd, M6 X 12 | 4 |
| 27C | 600210 | Screw, Button Hd, M8 X 12 | 4 |
| 28 | 600537 | Hex Coupling, 3/8-16 X 1-5/8 Long | 2 |
| 29 | 101160 | Threaded Rod 3/8-16 X 1.75 | 2 |
| 30 | 600528 | Hex Nut, #3/8-16 | 2 |
| 31 | 600103 | #8 X 1/2L Coarse Thread Screw (not shown) | 1 |
| 32 | 101056 | 2.00 Diameter Leveling Pad 3/8-16" | 2 |
| 33 | 101156 | Isolator Bracket | 2 |
| 34 | 101187 | Electrical Box | 1 |
| 35 | 100938 | IR Receiver, 60 CH 115v (not shown) | 1 |
| 36 | 100941 | IR Receiver Sensor, W/ 6' Cable (not shown) | 1 |
| 37 | 100608 | Rectangular Weight Bar .25 X 1.00 x canvas Width. (not shown) | 1 |
| 38 | 101194 | 2 channel IR Transmitter.(not shown) | 1 |
| 39 | 600131 | #8 X 1 1/2 Truss Head(not shown) | 6 |